



BULLETIN # B-112-2006-S

From: Parts and Service Division
To: All Authorized Service Agencies

Date: December 12, 2006

Subject: Design change to micro switch bracket
Models Affected: Garland MPOE5L Convection Ovens at Tim Hortons

Part # 4522011 door micro switch bracket kit has been designed & is a direct replacement for part # 1962106.

The re design of the bracket now includes

- Bracket
- Nutcerts
- 2 ea. 10-24 x 1/2 fasteners.

Micro Switches are NOT part of the kit

The new designed bracket will address problems with micro switch bracket coming out of position. Typically out of position bracket will result in the display indicating CLOSE DOOR when the door is in fact closed.

NEW bracket with nut certs attached

