



**BULLETIN # B-51-2007-S**

**From: Parts and Service Division**  
**To: All Authorized Service Agencies**

**Date: May 28, 2007**

**THIS BULLETIN SUPERCEDES BULLETIN NUMBER "B-50-2007-S"  
PLEASE REMOVE BULLETIN FROM YOUR FILE**

**Subject: Half Size Electric Moisture Plus Convection Oven Water  
Regulator Change part # 4518124**  
**Models Affected: MPOE5L ½ size electric convection ovens**  
**Tim Hortons locations only**

Starting serial number 0704100235307 ( 07 = 2007 04 = April ) the water regulator on the MPOE5L convection oven for Tim Hortons changed.

Units manufactured prior to above serial # were supplied with an AIRTROL water regulator. You can easily identify units with the AIRTROL as ones that do not have a pressure-indicating gauge.


Original AIRTROL regulator part # 4518124 is no longer used in the MPOE5L for Tim Hortons. Kit part # 4522822 will be required if the AIRTROL regulator fails.

When ordering replacement pressure regulators, please make note as to whether an AIRTROL or ASCO valve is in the unit. If an AIRTROL regulator complete kit part # 4522822 is required. If an ASCO regulator, only order parts that are required to complete the service call, as the complete kit would not be required.

**Please refer to attached pages showing original AIRTROL configuration and new ASCO configuration kit..**



**New ASCO Water Regulator Kit  
PART # 4522822**



Item #	Part #	Description	QTY
6	4517019	Cover Spritz Components	1
5	1935201	1/8" N.P.T X 1 1/2" Nipple	1
4	1934502	Pressure Gauge	1
3	8002107	Screw Philips #10 X 1/2"	2
2	1934501	Pressure Regulator ASCO	1
1	4522392	Bracket, Water Solenoid	1